

006227 6226/60




Fig. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 4




FIG. 5A




FIG. 5B




FIG. 6




FIG. 8




FIG. 9

PERTURBED
REGULAR GRID
192




FIG. 10




FIG. 11




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




Fig. 13C




Fig. 13D

Bin Identifications

| | | | | |
|-----|-----|-----|-----|-----|
| B3 | B4 | B5 | B6 | B7 |
| B11 | B12 | B13 | B14 | B15 |
| B19 | B20 | B21 | B22 | B22 |




Fig. 13E




FIG. 14





FIG. 15




FIG. 16

Fig. 17B




Fig. 17C

Fig. 17D




Fig. 17E




Fig. 17F




Fig. 18